

Bulletin Number: YATB2015-001-A_SA221/324/424_PTO SW Circuit_Mandatory requirement

SA221/324/424 IMPROVEMENT OF PTO SWITCH CIRCUIT

Effective Date: June 19, 2015

Dear Valued Yanmar Customers

At Yanmar America Corporation, we are committed to building high quality and a community of satisfied customers. We sincerely apologize for inconvenience.

AFFECTED MODEL(S): SA221, 324, 424

For impacted units shipped from Yanmar America before June 4th 2015

Condition

It has been reported that in some cases when significant amount of water is introduced to the PTO switch, the PTO switch may engage due to a short circuit when the PTO switch is in the OFF position.

Procedure

1. Please kindly contact your original purchasing dealership or nearby Yanmar dealership to perform this rework. Yanmar America will be providing rework parts to each affected Yanmar dealership as soon as possible but no later than July 10th, 2015.
2. The dealership will perform an installation update to the PTO harness on your unit.



Sincerely yours,
Liston Edge
Senior Service Manager, Customer Support Department
Yanmar America Corporation

Yanmar America Corporation
Tel: 1-855-416-7091
e-mail: cs_support@yanmar.com